

09/419439

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,839,833 B1
DATED : January 4, 2005
INVENTOR(S) : Thomas D. Hartnett, John S. Kuslak and Leroy J. Longworth

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page.


Item [54], Title, the terms "**PIPELINE DEPTH CONTROLLER FOR AN INSTRUCTION PROCESSOR**" should read -- **SYSTEM AND METHOD FOR CONTROLLING THE ENTRY OF INSTRUCTIONS INTO A PIPELINE OF AN INSTRUCTION PROCESSOR** --.

Column 24.

Line 2, the terms "pipeline-including" should read -- pipeline including --

Signed and Sealed this

Twelfth Day of April, 2005



JON W. DUDAS
Director of the United States Patent and Trademark Office